

SAFETY AND CONDUCT REGULATIONS - FACTORY TOUR

EMPL Fahrzeugwerk Ges.m.b.H.

In order to ensure that your visit to Empl is as comfortable, and in particular, as safe as possible, it is of utmost importance that our safety and conduct regulations are observed at all times:

- Ear protection should be worn when requested by your Empl guide.
- Protective glasses must be worn at all times in the workshops.
- Always keep to pre-signalled footpaths and transport routes and stay with the group at all times.
- Please observe marked safety areas / no smoking zones (lacquering, etc.).
- Look out for forklift and crane operation, in addition to all other in-company transport vehicles.
- Do not look directly into the arc during welding / flame cutting tasks
- Watch out for sparks during grinding work
- Do not walk under suspended loads
- Please remember that hot working parts can burn (when welding, grinding, hot straightening, etc.)
- Take care with parts lying on the floor, air hoses, electric cables, etc. (danger of tripping)
- Take care with any oil or lubricant spills on the floor (danger of slipping)
- Take care with sharp edges and corners (danger of injury) – especially with sheets and panels on the floor
- Take care near open assembly pits – danger of falling
- Photography and filming is not allowed

Failure to comply with the aforementioned safety regulations, or failure to respect instructions given by the Empl guide relieves Empl from all liability for any damage caused.

Stand: 07.2018